

TECHNICAL SERVICE BULLETIN - 1457

Technical

Information

TO: ALL GRAVELY OUTLETS

DATE: OCTOBER 31, 1973

SUBJECT: REPAIR KITS FOR DOUBLE UNIVERSAL DRIVE SHAFTS

We are using two suppliers for the above parts. They have different sizes on two of the dimensions of the universal. This requires two different repair kits.

The present repair kit is part number 12134P1.

The new repair kit is part number 20573P1.

To determine which repair kit you will require, check the drive shaft. The 12134P1 repair kit is used only on the shafts with the letters R.S. cast in the universal.

The new repair kit, number 20573P1, is used only on shafts with the letters N.B. cast on the universal.

an

M. H. Lance, Manager Customer Service Department

MHL/bh