



BATTERY SERVICE

Procedure for Activating Dry Charged Batteries

Step 1:

Fill each cell so that the plates and separators are covered with electrolyte, this permits the electrolyte to expand as battery is charged and prevents spillage from the charging process. Electrolyte of 1.265 specific gravity is recommended.

Step 2:

When using 1.265 electrolyte, charge 12 volt batteries at 30 amps for 20 minutes until the specific gravity is 1.255 - 1.265 and the electrolyte is 80°F.

Step 3:

After charging, check electrolyte level in all cells. Fill with electrolyte as required to proper level.

mercial 12) a rate of 3 amps for 12 hours is recommended or until gravity is in a range of 1.255 - 1.265. For Gravely Battery part number 15256P1 (408) a rate of 2 amps for 12 hours is recommended or until gravity is in a range of 1.255 - 1.265.

(3) Trickle Charge:

Is a continuous charge at a low rate sufficient to compensate for the internal losses of the battery and suitable to maintain the battery in a fully charged condition. Low-rate charges are satisfactory, provided the total amount of charge received by the battery is adequate to cover the local action. Trickle charging only maintains the charge, it neither adds to the state of charge or diminishes the state of charge.

Battery Charging Rate and Time Table For Activating

12 Volt Battery

Battery Charge Recommendations	AMPS	HOURS	MINUTES
(1) Fast Charge:	30	20	20
30 amp rate for initial activation of dry charge. (See Chart)	25	24	24
	20	30	30
	15	40	40
	10	1	0
	8	1	15
	6	1	40
	4	2	30
	2	5	0
(2) Slow Charge:			

For Gravely Battery part number 72774P1 (424, 430, 432, 450, Convertible 7.6, Commercial 10-A, Com-