

Date: July 5, 1979

File Reference: D.I.B. "E"

File Duration: Permanent

To: All Gravely Dealers, Branches and Distributors

Subject: **Parts Changes**

Kohler has advised Gravely that part #21137, engine, is being cancelled and will no longer be available. The engine will be serviced by part #18783, miniblock.

The following parts have been cancelled or replaced by a different part number.

12041	Bearing Plate	Replaced by	24886
12149	Ring Gear	Cancelled	
13256	Spiral Bevel Pinion Shaft	Cancelled	
14348	Bendix Coil	Cancelled	
14770	Screw	Replaced by	24868
15378	Housing	Replaced by	24673
15387	Breather Reed	Replaced by	18608
15388	Breather Plate	Replaced by	18608
15856	Conduit Asm.	Cancelled	
17981	Body Core	Cancelled	
18477	Piston Pump	Cancelled	
18620	Ring Gear	Cancelled	
18748	Cap End	Replaced by	24875
20573	Repair Kit	Replaced by	24560
22838	Bolt	Replaced by	22325
23124	Repair Kit	Cancelled	
23874	Oil By Pass Valve	Cancelled	
23972	Lower Body	Cancelled	
24029	Exh. Muffler	Cancelled	
24067	Trans Drive Gear	Cancelled	
24068	Trans Gear	Cancelled	
24112	Housing	Cancelled	
24114	Loop Type Clamp	Cancelled	
24182	Overhaul Kit	Cancelled	

24864	Camshaft Pin	Replaced by	10783
24871	Cyl. Block	Replaced by	19902
24876	Drive Kit	Replaced by	18753
24932	Camshaft	Replaced by	18609
24941	Lead	Replaced by	11822
24976	Cyl. Block	Cancelled	

Please change your records accordingly.



Alfred D. Hutchens  
Parts Supervisor