

TECHNICAL SERVICE BULLETIN – 1463**TO: ALL GRAVELLY OUTLETS****DATE: FEBRUARY 5, 1974****SUBJECT: FRONT WHEEL ASSEMBLIES ON 800 SERIES
TRACTORS, PART NUMBER 18443A1**

During a recent Quality Assurance Set Up Check of an 800 Series Tractor, it was noted the front wheels did not fit properly.

Investigation determined the wheel manufacturer has pressed the bearing races too far into the wheel, breaking the race stops.

This condition will not allow the front wheels to be tightened in the normal manner.

We have sent 1,500 wheels back to our supplier; however, approximately 300 tractors have been shipped with the incorrect wheels. Do not use these wheels; they will be replaced by the wheel manufacturer. Send the defective wheels to:

Geneva Metal Company
Cartersville, Georgia 30120



M. H. Lance, Manager
Customer Service Department

MHL/bh