

To continue its program of quality and design improvement, the manufacturer reserves the right to change specifications, design or prices without notice and without incurring obligation.

## Technical Information

## TECHNICAL SERVICE BULLETIN - 1462

TO: ALL GRAVELY OUTLETS

DATE: FEBRUARY 5, 1974

SUBJECT: CHANGE IN KNOB AND LEVER ASSEMBLY USED ON CHOKE AND THROTTLE CONTROL OF RIDING TRACTORS,
PART NUMBER 11773P1

The present parts are approximately 1/32 of an inch thicker than the old ones.

On some of the old riding tractors, you may notice interference when using the new lever assembly as a replacement.

Should you find this condition, grind the lever to allow clearance.

The interference will be between the wider lever and the small brackets welded to the underside of the instrument panel.

M. H. Lance, Manager

**Customer Service Department** 

MHL/bh