

Technical Information

TECHNICAL SERVICE BULLETIN - 1464

TO: ALL GRAVELY OUTLETS

DATE: FEBRUARY 20, 1974

SUBJECT: CANCELLATION OF PART 18013P1, TWO SPEED RAIL AND PART 18014P1, TWO SPEED YOKE

The above two parts are being replaced by part number 20755A1. The new part is a welded fabrication.

The change is caused by the unavailability of the 18014P1 yoke in powdered metal.

This change has started with tractor serial number 20761A.

The new part will fit in all previous manufactured 800 series tractors.

M. H. Lance, Manager

Customer Service Department

MHL/bh