

**TECHNICAL SERVICE BULLETIN – 1465****TO: ALL GRAVELLY OUTLETS****DATE: FEBRUARY 20, 1974****SUBJECT: CANCELLATION OF PART 14643P1 BEVEL GEAR PINION,  
USED IN 40" AND 50" MOWER DRIVE**

The above part can no longer be obtained as a forged gear. We must now cut the teeth.

The new piece with the cut teeth will not mesh with the forged teeth on the mating gear. For this reason, should it become necessary to replace part 14643P1, the mating part (11220P1) will also have to be replaced.

On any future orders for 14643P1, we will supply a replacement kit, part number 20747A1 which will include two (2) parts. One each of 19706P1 and 19608P1.



M. H. Lance, Manager  
Customer Service Department

MHL/bh