

To continue its program of quality and design improvement, the manufacturer reserves the right to change specifications, design or prices without notice and without incurring obligation

Technical Information

TECHNICAL SERVICE BULLETIN - 1482

TO: ALL GRAVELY OUTLETS

DATE: OCTOBER 15, 1974

SUBJECT: CHANGE IN WIRING HARNESS ON 816 TRACTORS

STARTING WITH SERIAL NUMBER 24270

Starting with the above serial number, the wiring harness, part number 20749P1, will include the two wires to the oil light and engine shroud fuse.

These wires are presently part of the positive battery cable, part number 15747P1. They will be removed from the cable at the time of adding them to the harness.

Battery cable, 15747P1, will be retained for service. A new part number will be assigned to the cable without the two wires. The new number is 20889P1.

Service availability on the parts.

20749P1 Used on all tractors

15747P1 Retained for service on tractors before serial number

24270

20889P1 Used on tractors after serial number 24270

Should it become necessary to use the new wiring harness (with the two added wires) on a tractor before serial number 24270, cut off the two wires on the positive battery cable as it will allow easier service on the electrical system in the future if it should be required.

M. H. Lance, Manager

Customer Service Department

MHL/bh