

To continue its program of quality and design improvement, the manufacturer reserves the right to change specifications, design or prices without notice and without insuring obligations.

## Technical Information

TECHNICAL SERVICE BULLETIN - 1480

TO: ALL GRAVELY OUTLETS

DATE: SEPTEMBER 30, 1974

SUBJECT: CHANGE IN PAINT SPECIFICATIONS ON 34", 40" AND 50" THREE SPINDLE ROTARY MOWERS

The right and left hand drive assemblies on the 34" mower will not be painted from this date.

The 40" and 50" three spindle drive assembly and spindle assemblies will not be painted from this date.

These changes are being made to reduce the grease leaks on the mowers.

M. H. Lance, Manager

**Customer Service Department** 

MHL/bh